

1. IDENTIFICATION OF THE SUBSTANCE/MIXTURE AND OF THE COMPANY/UNDERTAKING

1.1 PRODUCT IDENTIFIER	5NT – Copper alloy
1.2 RELEVANT IDENTIFIED USES OF THE SUBSTANCE OR MIXTURE AND USES ADVISED AGAINST	Alloy for goldsmith and precious jewelry
1.3 DETAILS OF THE SUPPLIER OF THE SAFETY DATA SHEET	<p>Pandora Alloys srl Via Galvani, 14 20094 Corsico (MI) Italia</p> <p>+39 02 45 86 40 35 +39 02 45 86 98 40 info@pandoralloys.com www.pandoralloys.com</p>
1.4 EMERGENCY TELEPHONE NUMBER	<p>Centro antiveleni c/o Niguarda Hospital P.za Ospedale Maggiore, 3 Milano – Italy</p> <p>+39 02 66 10 10 29 (24h)</p>

2. HAZARDS IDENTIFICATION

2.1 SUBSTANCE CLASSIFICATION FURTHER HAZARDS	None to report.
---	-----------------

3. COMPOSITION / INFORMATION ON INGREDIENTS

Cu, Ag, Zn - NOT DANGEROUS

4. FIRST AID MEASURES

4.1 DESCRIPTION OF FIRST AID MEASURES AFTER SMOKE INHALATION	It's good practice melting under extraction hoods or in closed casting machines, in case of fumes inhalation ventilate the room. In case of illness seek medical advice.
AFTER CONTACT WITH SKIN	No danger reported from normal use. Seek medical advice in presence of known sensitivity. In case of contact with molten metal, evaluate the extent of the burn and seek medical attention.
AFTER CONTACT WITH EYES	In event of irritation from fumes oxide, rinse with water. Consult your doctor if you develop conjunctivitis.
AFTER INGESTION	No risks reported.
4.2 MAIN SYMPTOMS AND EFFECTS, BOTH ACUTE AND DELAYED	Vapor / fumes / dust: coughing, sneezing or lacrimation. In case of repeated or prolonged exposure, possible gastrointestinal disturbances, breathing difficulty, hypotension, cramps, and fever. Symptoms can occur with a certain delay.
4.3 INDICATION OF THE POSSIBLE NEED OF IMMEDIATE MEDICAL ADVICE OR SPECIAL TREATMENTS	Follow the procedures of safety agreed in your company

SCHEMA DI SICUREZZA

REDATTA IN CONFORMITA' AL REGOLAMENTO CE N.1907/2006

5NT

13.09.2016

Rev. 1

Pag. 1 di 4

5. EXTINGUISHING METHODS

- 5.1 Extinguishing media
 Recommended extinguisher None in particular
 Forbidden extinguisher Do not use water on molten metals
- 5.2 Special dangers due to the substance or to the mix
 None in particular. Molten alloy might release smokes and vapor made up of oxides.
- 5.3 Recommendations to the employees in charge of fire extinction
 Use adequate protections in case of smokes.
 Follow the procedures of extinguishing agreed in your company.

6. MEASURES IN CASE OF ACCIDENTAL RELEASE

- 6.1 Personal precautions, protection devices and procedures in case of emergency
 Inert material. Use individual protection devices in case of certain sensibility to the mix. Use protection devices in case of exposition to vapors and smokes. During working time, follow the safety procedures agreed in your company.
- 6.2 Environmental precautions
 Avoid release in the environment
- 6.3 Methods and materials for containment and collection
 Collect material using devices suitable to re-use the material itself and/or its recovery by the producer.
- 6.4 reference to other sections
 See sections 8 e 13

7. HANDLING AND STORAGE

- 7.1 Precautions for a safe handling
 Alloys can be handled without any particular precaution. During casting, melting, mechanical works, annealing and welding, provide for ventilation. Do not breathe dust, vapors and smokes.
- 7.2 Conditions for a safe storage, including possible incompatibilities.
 Alloys can be stored without any particular precaution. For a better use, it is suitable a covered and dry place for storage.
- 7.3 Final specific uses
 Copper alloy to be molten with pure gold.

8. EXPOSITION CONTROL/PERSONAL PROTECTION

- 8.1 Control parameters
 Limit values for zinc oxide TLV-TWA - smokes: 5 mg/m³, dusts: 10 mg/m³
- 8.2 Controls of exposition
- | | |
|------------------------|--|
| Respiratory protection | Workplace should be ventilated, in case of need use protective masks and aspiration while casting. If aspiration devices are not available, use a ventilation device suitable for casting process. |
| Hands protection | Use gloves suitable for casting. |
| Eyes protection | Use protective glasses while casting. |
| Skin protection | Use protective clothes and gloves |

13. DISPOSAL CONSIDERATION

13.1 Methods of waste treatment	Reuse if possible. Follow the procedures and laws of your Country.
---------------------------------	---

14. INFORMATION ON TRANSPORT

14.1 UN number	n.a.
14.2 UN shipping rule	n.a.
14.3 Class of danger referred to transport	n.a.
14.4 Packing group	n.a.
14.5 Danger for environment	n.a.
14.6 Special precautions for users	n.a.
14.7 Collect transport according to Marpol 73/78 and IBC code	n.a.

15. INFORMATION ON REGULATIONS

15.1 Rules and laws on health, security and environment, specific for the mix	This chart follows the directions of CE Rule 1907/2006
---	--

15.2 Chemical safety value	no
----------------------------	----

16. OTHER INFORMATION

This chart has been written as per our knowledge at the present date. The user is asked to check if information are suitable and complete referred to the use of the alloy. Information on this chart are a description of characteristics of this product about its safety; this chart is not a guarantee of properties of this product.

This chart substitutes every previous communication.